

REPORT of SURVEY for REPAIRS.

4588

AS

No. 4588 Survey held at London Date Sept 27th 1838
 on the Ship Australia Master English
 Tonnage 373 Built at Buckley When built 1825
 By whom built _____ Owners English & Co
 Port belonging to Liverpool Destined Voyage Bahia
 If Surveyed Afloat or in Dry Dock Smith's Dock

Original Survey, No. 106723153 Dated 1835 Classed 104-1
 Port London 1837 F. 1
Port

Repairs At the present time copper stripped. Broothatching executed
 spiled & caulked & Copied to 18.6
 Has had a new Rudder fitted at Rio Janeiro
 generally overhauled aloft
 Has been supplied with the additional Anchor & Chain Cable
 Nov 2nd 1838 W. M. D. S.

The Surveyor is also required to state the present Condition of the

Decks <u>Good</u>	Transoms _____	Windlass <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame _____	Capstan _____
Lower Deck Beams & Fastenings <u>Good</u>	Topsides <u>Good</u>	Pumps _____
Spirkettling _____	Wales _____	Masts, Yards, &c. <u>Overhauled</u>
Plank Shears _____	Counter <u>Good</u>	Sails <u>Good sufficient</u>
Waterways <u>Trim</u>	Plank & Treenails <u>Good</u> (Outside to the Water's Edge)	Cables <u>Wants 1 Anchor & some additional cable</u>
Hatchway Comings <u>Good</u>	Rudder <u>New 1838</u>	Anchors No. of <u>3</u>
Breasthooks _____	Copper <u>18.6 1838</u>	Standing & Running Rigging <u>Overhauled good</u>

General Observations and Opinion, This Ship presents a firm appearance and when she has
 as required by the Instructions, of the additional Anchor & Chain, which were stated to have
been ordered when I surveyed her. She will be fully eligible
to remain as classed F. 1 George Bayley

The Amount of Fee.....£ 1 : 1 : - is received by me, AS

Committee Minute 30th Oct 1838

Character assigned continues F.
Insert figure one on his figures

