

# REPORT of SURVEY for REPAIRS.

No. 4716 Survey held at London Date Nov<sup>r</sup> 12<sup>th</sup> Dec<sup>r</sup> 1838  
 on the Schooner Champion Master \_\_\_\_\_  
 Tonnage 302 Built at Montrose When built 1826  
 By whom built \_\_\_\_\_ Owners J. Pounce  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Fountain Dock, Shipway during Repair

Original Survey, No. 2366 & 4404 Dated \_\_\_\_\_ Classed A. 1  
 Port London

**Repairs** At the present time All most of Frame of English and  
 African Oak, Inner Post, Stern Timbers, several of  
 the Quarter Timbers on each side, about 12 or 13 Stakes  
 on each side abaft - a quantity of Ceiling & Trussing  
 knees shifted - 4 Pair of Iron Hanging Knees put to  
 Hold Beams -

It is stated (which is confirmed by the appearance of the Plank)  
 that a quantity of Plank, was shifted in the Topsides and in  
 the Decks when at Canton during her last voyage -

The Surveyor is also required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>None</u>	Windlass _____
Upper Deck Beams & Fastenings <u>4</u>	Timbers of the Frame <u>Good</u>	Capstan _____
Lower Deck Beams & Fastenings <u>4</u>	Topsides <u>Good</u>	Pumps _____
Spirkettling <u>4</u>	Wales <u>4</u>	Masts, Yards, &c. <u>Good &amp; efficient</u>
Plank Shears <u>4</u>	Counter <u>None</u>	Sails _____
Waterways <u>4</u>	Plank and Treenails <u>Good</u> (Outside to the Water's Edge)	Cables _____
Hatchway Comings <u>4</u>	Rudder <u>4</u>	Anchors No. of _____
Breasthooks _____	Copper <u>Single</u>	Standing & Running Rigging _____

General Observations and Opinion,  
 as required by the Instructions,

"The present repair has been carried as far as any  
 defective Timbers or Plank, could be found abaft this  
 with the additional security to the Hold Beams under  
 her in my opinion eligible to be Classed A. 1"

The Amount of Fee.....£ 1 : 1 : - is received by me, George Bayley

Committee Minute 11<sup>th</sup> Dec<sup>r</sup> 1838

Character assigned A. 1 Record Repairs Good