

REPORT of SURVEY for REPAIRS.

No. 4755 Survey held at London Date Dec 10 18 38
 on the Bark Marlborough Master Bridge
 Tonnage 321 Built at Lynn When built 1822
 By whom built _____ Owners Green & Co
 Port belonging to London Destined Voyage Samoa
 If Surveyed Afloat or in Dry Dock Shed "furling" Dry Dock

Original Survey, No. 943, 2108 Dated September 1838 Classed *A. 1
 Port London

Repairs At the present time the Wing and five other Transoms shifted together with 13 Stakes on the Starboard side aft of & on the Larboard side, the Planks in wake of the Chain Bolts, caulked throughout upper Course broodsheathed & letted & coppered.

W. The five planks remaining in the Larboard Quarter have been recently shifted. Liners of the frame when exposed good sound.

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

In my opinion this ship should remain
 as classed *A. 1

George Bayley

The Amount of Fee.....£ 2 : 2 : - is received by me,

Committee Minute 21 Dec 18 38

Character assigned A. 1