

ANNUAL SURVEYS.

4880

No. 4880 Survey held at London Date Jan'y 25th 1839
 on the Bg City of Genoa Master Harv
 Tonnage 152 Built at Dartmouth When built 1819
 By whom built _____ Owners _____
 Port belonging to London Destined Voyage Brazil
 If Surveyed Afloat or in Dry Dock on the Mags

Original Survey, No. 1164/1895 Port of London 1838 Classed E 1

The Surveyor is required to state the present Condition of the

Decks <u>Indifferent</u>	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirketting <u>Fair</u>	Topsides <u>Fair</u>	Sails <u>Good</u>
Plank Shears <u>condition</u>	Wales <u>condition</u>	Cables <u>Sufficient</u>
Waterways _____	Plank and Treenails _____	Anchors No. of _____
Hatchway Comings _____	(Outside to the Water's Edge)	Standing & Running Rigging _____
	Rudder _____	Copper _____
	Windlass _____	

General Observations and Opinion, At the present time bottom examined the Copper
 as required by the Instructions, patched, several pieces let into the Decks & the
upper works caulked, I am of opinion is only entitled
to her present class

Committee Minute 5 Feb 1839

Character assigned E 1

No. 123 Survey held at London Date January 26th 1839
 on the St Isabel Master John Ross
 Tonnage 123 Built at Hastings When built 1831
 By whom built _____ Owners J & J Adam
 Port belonging to London Destined Voyage St Michael's
 If Surveyed Afloat or in Dry Dock on the Mags

Original Survey, No. 2508/3008 Port of London Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks _____	Breasthooks _____	Capstan _____
Upper Deck Beams & Fastenings _____	Transoms _____	Pumps _____
Lower Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Spirketting <u>Good</u>	Topsides _____	Sails <u>Good</u>
Plank Shears _____	Wales <u>Good</u>	Cables <u>Good</u>
Waterways _____	Plank & Treenails _____	Anchors No. of _____
Hatchway Comings _____	(Outside to the Water's Edge)	Standing & Running Rigging _____
	Rudder _____	Copper _____
	Windlass _____	

General Observations and Opinion, At the present time part new covering board in consequence
 as required by the Instructions, of damage waterways caulked & bottom examined
is in a very high state of efficiency and may continue
her present class

Committee Minute 5 Feb 1839

Character assigned 12 A 1



© 2019

Lloyd's Register
Foundation

15704-0237