

5047

REPORT of SURVEY for REPAIRS.

No. ³⁵¹ Survey held at London Date Oct^r 24 1836
on the Barb Bombay Master Hellaway
Tonnage 1280 Built at Bombay When built 1809
By-whom built _____ Owners H Temple
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Ship^r Hatched & Dry Dock

Original Survey, No. _____ Dated 1834 Classed F.1
Port London

Repairs. At the present time caulked from keel up and
the hull overhauled - recoppered -

The Surveyor to state the present Condition of

Upper Deck Fastenings	} <u>Good</u>	Wales	} <u>Good</u>
Spirketting		Counter	
Plank Shears		Plank and Treenails (Outside to the Water's Edge.)	
Topsides		Rudder	
Upper Deck with its Appendages		<u>Widened</u>	
Lower Deck Fastenings		Capstan	

General Observations and Opinion, There are no appearances of straining breakings
as required by the Instructions, or decay discoverable in this ship at the present
time - She is in my opinion entitled to remain
in her present class - George Bayley
Attains out of
2 Dock

The Amount of Fee..... £ : : is received by me.

Committee Minute _____ 183 _____

Character assigned _____