

ANNUAL SURVEYS.

5068

No. ³⁷ Survey held at London Date March 26th 1839
 on the Bk Ocean Master Robertson
 Tonnage 271 Built at Whitby When built 1797
 By whom built _____ Owners Bourgois
 Port belonging to London Destined Voyage Pugnash
 If Surveyed Afloat or in Dry Dock in the Surrey Canal

Original Survey, No. 1102, 2318 Port of London 1037 Classed E, 1
3282, 3655,

The Surveyor is required to state the present Condition of the

Decks	Breasthooks <u>Sound</u>	Capstan
Upper Deck Beams & Fastenings	Transoms <u>"</u>	Pumps
Lower Deck Beams & Fastenings <u>Very fair</u>	Timbers of the Frame <u>Fair condition</u>	Masts, Yards, &c.
Spirketting <u>Condition</u>	Topsides <u>"</u>	Sails <u>Well</u>
Plank Shears	Wales <u>"</u>	Cables <u>frank</u>
Waterways	Plank and Treenails <u>"</u> (Outside to the Water's Edge)	Anchors No. of
Hatchway Comings	Rudder <u>"</u>	Standing & Running Rigging
	Windlass <u>"</u>	<u>Copper</u>

General Observations and Opinion, At the present an Iron brace outside the quarter &
as required by the Instructions, stand the Sternpost bolted to the second Transom.
Sealing repaired & caulked, I am of opinion is
good condition to retain her present shape

Committee Minute 28 March 1839

Character assigned E, 1

Change of Owners

No. ³⁸ Survey held at London Date March 26th 1839
 on the By Trees Master Beswick
 Tonnage 121 Built at Stockton When built 1025
 By whom built _____ Owners J. Hays
 Port belonging to Stockton Destined Voyage Stockton
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 3361 Port of Stockton 1037 Classed A, 1

The Surveyor is required to state the present Condition of the

Decks <u>Fair condition</u>	Breasthooks <u>upper one decayed</u>	Capstan <u>none</u>
Upper Deck Beams & Fastenings <u>Works</u>	Transoms <u>Fair</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>not seen</u>	Masts, Yards, &c. <u>"</u>
Spirketting <u>"</u>	Topsides <u>Good</u>	Sails <u>Well frank</u>
Plank Shears <u>Indifferent</u>	Wales <u>"</u>	Cables <u>"</u>
Waterways <u>"</u>	Plank & Treenails <u>"</u> (Outside to the Water's Edge)	Anchors No. of <u>"</u>
Hatchway Comings <u>Good</u>	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
	Windlass <u>"</u>	<u>Copper</u>

General Observations and Opinion,
 as required by the Instructions,

The upper Breasthook is decayed, Decks on is
forward decayed, works at the Beam end & water-
way seam, covering board defective & the railing
very indifferent, I am of opinion she is not fit for
safe conveyance & dry & purchase cargo

Committee Minute 28 March 1839

Character assigned

See Stockton Survey No 80