

REPORT of SURVEY for REPAIRS.

5434

No. _____ Survey held at London Date July 3rd 1839
 on the Bk Warrior Master H. Povey
 Tonnage 307 Built at Dundee When built 1837
 By whom built _____ Owners J & Blum 2^d Owners
 Port belonging to Dundee Destined Voyage Cape of Good Hope
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. _____ Dated 1837 Classed 7 A 1
 Port of Dundee

Repairs *At the present time bottom stripped, caulked from the keel upwards, Copper over paper & Iron hanging Diagonal knees to the Deck Beams —
 Two Brackets —*

London 5434

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <i>Good</i>
Plank Shears	Counter	Sails <i>Good</i>
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables <i>sufficient</i>
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, *This vessel is in a very high state of efficiency both as required by the Instructions, in the Hull & Stores & eligible to retain her present Class*

M. Middleton

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18____

Character assigned See annexed Survey

