

REPORT of SURVEY for REPAIRS.

5553

No. _____ Survey held at London Date January 19th 1839
 on the Brig Milton Master J. C. Dunn
 Tonnage 242 Built at Thorn When built 1827
 By whom built _____ Owners J. Brubay
 Port belonging to London Destined Voyage Dryden
 If Surveyed Afloat or in Dry Dock Gun Dock

Original Survey, No. _____ Dated 1830 Classed * A. 1
 Port of London See 5553 annexed

Repairs At the present time Bottom caulked, sheathed with yellow metal over felt to the 10 feet mark

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>of sufficient</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, I am a very efficient state both in the Hull & Stores
as required by the Instructions, and I am of opinion is fit for the safe conveyance
of Dry & perishable cargoes to & from all parts of
the World & may retain her present class

The Amount of Fee.....£ 1 : 1 : _____ is received by me, [Signature]

Committee Minute _____ 18 _____

Character assigned See Annexed Survey