

ANNUAL SURVEYS.

5614

No. ³⁸² Survey held at London Date Sept 6th 1839
 on the Sp Sir John Rae Reid Master Dyson
 Tonnage 327 Built at London When built 1828
 By whom built _____ Owners Manning & Co
 Port belonging to London Destined Voyage St Kitts
 If Surveyed Afloat or in Dry Dock in the London Dock

Original Survey, No. 877, 4264 Port of London
5133

Classed 12 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks <u>Sound</u>	Capstan <u>Good</u>
Upper Deck Beams & Fastenings	Transoms <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings	Timbers of the Frame <u>sound & sound</u>	Masts, Yards, &c. <u>"</u>
Spirkettling <u>Good</u>	Topsides <u>Good</u>	Sails <u>Well found</u>
Plank Shears	Wales <u>"</u>	Cables <u>"</u>
Waterways	Plank and Treenails <u>"</u> (Outside to the Water's Edge.)	Anchors No. of <u>"</u>
Hatchway Comings	Rudder <u>"</u>	Standing & Running Rigging <u>Good</u>
	Windlass <u>"</u>	Copper <u>"</u>

General Observations and Opinion, At the present time called from the Upper upwards
 as required by the Instructions, & the rigging overhauled, is in a very efficient state
and may retain her present Character

Committee Minute 13 Sept 1839
 Character assigned 12 A 1

W. M. M. M.

No. 150 Survey held at London Date Sept 9th 1839
 on the Bk The "Carty" Master Philly
 Tonnage 254 Built at Sunderland When built 1834
 By whom built _____ Owners Carty & Co
 Port belonging to Droghda Destined Voyage Demerara
 If Surveyed Afloat or in Dry Dock in Gun Dock

Original Survey, No. _____ Port of London

1030 Classed 11 A 1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling <u>Good</u>	Topsides	Sails <u>Good</u>
Plank Shears	Wales <u>Good</u>	Cables <u>"</u>
Waterways	Plank and Treenails <u>"</u> (Outside to the Water's Edge)	Anchors No. of <u>sufficient</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, At the present time called from the Upper to the Gunwale
 as required by the Instructions, Copper patched, two planks in the Starboard Buttock
shifted being worn eating & a general overhaul
is now in good condition & may continue as before

Committee Minute _____ 183
 Character assigned _____

W. M. M. M.
 © 2019
 Lloyd's Register
 Foundation