

ANNUAL SURVEYS.

5680

No. 637 Survey held at London Date Sept 24th 1839
 on the By Anne Master Hutton
 Tonnage 176 Built at Sunderland When built 1833
 By whom built _____ Owners Bay St.
 Port belonging to London Destined Voyage Spain
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 53 3391 Port of London 1837 Classed 10 A 1

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|---|----------------------------|
| Decks | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirkettling | Topsides | Sails |
| Plank Shears | Wales | Cables |
| Waterways | Plank and Treenails (Outside to the Water's Edge.) | Anchors No. of |
| Hatchway Comings | Rudder | Standing & Running Rigging |
| | Windlass | Copper |

Good *Good* *Good* *Efficient*

General Observations and Opinion, *Is altogether in a very efficient state & may*
 as required by the Instructions, *continue as before*

Committee Minute 1 Oct 1839

Character assigned 10 A 1

No. 410 Survey held at London Date Sept 26th 1839
 on the By Princess Victoria Master Sergison
 Tonnage 250 Built at Sunderland When built 1831
 By whom built _____ Owners Roman
 Port belonging to London Destined Voyage Newcastle & America
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 2006 Port of Liverpool, London 3884 Classed 9 A 1

The Surveyor is required to state the present Condition of the

| | | |
|-------------------------------|---|----------------------------|
| Decks | Breasthooks | Capstan |
| Upper Deck Beams & Fastenings | Transoms | Pumps |
| Lower Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Spirkettling | Topsides | Sails |
| Plank Shears | Wales | Cables |
| Waterways | Plank and Treenails (Outside to the Water's Edge.) | Anchors No. of |
| Hatchway Comings | Rudder | Standing & Running Rigging |
| | Windlass | Copper |

Good *Good* *Well* *Good*

General Observations and Opinion, *At the present time bottom examined on the Mags,*
 as required by the Instructions, *and caulked from the Copper to the Gunwale,*
in very good condition and may continue as before

Committee Minute 1 Oct 1839

Character assigned 9 A 1



© 2019

Lloyd's Register
Foundation