

# REPORT of SURVEY for REPAIRS.

5770

No. 98 Survey held at London Date Aug<sup>r</sup> 1839  
 on the Adelaide Master Campbell  
 Tonnage 640 Built at Calcutta When built 1832  
 By whom built \_\_\_\_\_ Owners Homes  
 Port belonging to London Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Original Survey, No. 2146, 3135 Dated \_\_\_\_\_ Classed 12 A 1  
 Port London 5397

**Repairs**

The Surveyor is also required to state the present Condition of the

Decks _____ Upper Deck Beams & Fastenings _____ Lower Deck Beams & Fastenings _____ Spirketting _____ Plank Shears _____ Waterways _____ Hatchway Comings _____ Breasthooks _____	Transoms _____ Timbers of the Frame _____ Topsides _____ Wales _____ Counter _____ Plank and Treenails <small>(Outside to the Water's Edge)</small> Rudder _____ Copper _____	Windlass _____ Capstan _____ Pumps _____ Masts, Yards, &c. _____ Sails _____ Cables _____ Anchors No. of _____ Standing & Running Rigging _____
--	---	--

General Observations and Opinion,  
 as required by the Instructions,

None to Mr Homes since last reported

Courtney

The Amount of Fee.....£ 3 : 3 : - is received by me, *MS*

Committee's Minute 1 Nov 1839

Character assigned 12 A 1

