

REPORT of SURVEY for REPAIRS.

5837

No. 457 Survey held at London Date Nov 26 22nd 1837
 on the Ship Sophia Master McNair
 Tonnage 537 Built at Calcutta When built 1813
 By whom built _____ Owners McNair
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Blackwall

Original Survey, No. 4330 Dated July 1838 Classed *F.1
 Port London

Repairs *At the present time chain and iron
 Channels taken off, & examined
 behind - several holes open - Caulked
 from keel up - Shirts & planks
 on Larboard Beam - and coppered to B.b
 Thoroughly overhauled in Hull Masts & Rigging*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

*In my opinion this Ship is fully eligible to
 remain as classed *F.1*
George Raper

The Amount of Fee.....£ 1 : 1 : - is received by me, *MS*

Committee's Minute 26 Nov 1837

Character assigned *F.1 *MS*

