

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at LONDON Date February 2^d 1840
 on the M^{rs} Champion Master Spencer
 Tonnage 287 Built at Sunderland When built 1835
 By whom built _____ Owners Indoors
 Port belonging to LONDON Destined Voyage _____
 If Surveyed Afloat or in Dry Dock St Katharine's Dock

Sunderland 349
 Original Survey, No. 4721, Dated 1838 Classed 10 A 1
 Port LONDON

Repairs

The keelson of this vessel being of Turpentine
 precludes her from an higher class than
 that at present assigned to her
 She is in most excellent condition and
 is fully entitled to her present class 10 A 1

George Bayley

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

The Amount of Fee £ : : is received by me,

Committee's Minute 25th Febry 1840

Character assigned 10 A 1