

REPORT of SURVEY for REPAIRS.

6096
L.H.

No. 114 Survey held at London Date Feb 21 1840
 on the Ship Larkins Master Ingram
 Tonnage 701 Built at Calcutta When built 1808
 By whom built _____ Owners Ingram
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Superintendent Dry Dock

Original Survey, No. 1818, 3805 Dated March 1839 Classed A.1
 Port London 5306,

Repairs

at the present time having been ashore
 shipped and fitted up and
 repaired & the damages efficiently
 repaired

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <u>Re-handling</u>
Plank Shears <u>Good</u>	Counter <u>Good</u>	Sails <u>Good</u>
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables <u>Good</u>
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>Re</u>	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

In my opinion this ship is eligible to remain
 as at present classed A.1

George Bayley

The Amount of Fee.....£ 1 : 1 : is received by me, SS

Committee's Minute 28th Febry 1840

Character assigned A.1 Asterisk Record Repair

