

REPORT of SURVEY for REPAIRS.

& Continuation

6176

No. _____ Survey held at London Date March 18 40
 on the By Glenalmon Master Young
 Tonnage _____ Built at Wanderland When built 1820
 By whom built _____ Owners J. Barnes
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock in the Dry Dock

Original Survey, No. _____ Dated _____ Classed _____
 Port _____

Repairs At the present time not a nail from the Copper to the Gunwale, one pair of Iron hanging braces to the Head Beam at aft the Mainmast, an Iron Cutch aft, one plank in the starboard Bow shifted in in the starboard quarter, new Channels, additional bolts in all the upper & lower Deck fastenings & caulked and a general overhaul in the Hull & Rigging. The Waterways, Beams, House timbers, Wroughthead, Breasthooks, Transoms, Floors, Helms, Planking outside & inside, Frame when seen Decks & Comings all in good condition, the Sheer & general form appear in its original shape

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion, as required by the Instructions, *There is some doubt as to the quality of the Ceiling; from its general appearance wear of grain it is English & African, it is also in short lengths shifted top & butt, and from the efficient state the is in throughout it may be continued for as many years as the first of the First Class as the rules will admit. The ceiling is English and African Oak, decidedly except 3 strokes in the flat which has the appearance of English Oak, but from the quantity of ballast she has on board we cannot decide positively.*

The Amount of Fee £ _____ is received by me,
 Committee's Minute 24th March 18 40

Character assigned _____