

ANNUAL SURVEYS.

6302

No. 233 Survey held at London Date 16 April 1840
 on the Ship William Harris Master Perry
 Tonnage 342 Built at Whitby When built 1816
 By whom built Bany Owners Bany
 Port belonging to Whitby Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Stamans dock

Original Survey, No. 5 Port of Whitby, Lon. 3333, 4655, 6068, Classed *A.

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails <small>(Outside to the Water's Edge)</small>	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, as required by the Instructions, *This ship after loading in the London docks made water, discharged part of the cargo, shipped 3 strakes of the upper course found a shabby plank 2nd strake under the wale, which led to a leaky hole where she had evidently made water*

Committee Minute 24th April 1840
 Character assigned First Mate *Wm. J. Clark*

No. 12 Survey held at London Date 20th April 1840
 on the Ship Barque Ida Master Paisley
 Tonnage 459 Built at London When built 1804
 By whom built Messrs. Barnards & Co. Owners Smith & Co.
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Kings dock

Original Survey, No. 2891, 3282 Port of London Classed A.
4192, 4574, 4853

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails <small>(Outside to the Water's Edge)</small>	Anchors No. of
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, as required by the Instructions, *The ship has made water abaft, stripped part of the bottom & found the hatch in the stem hole on the Lar. side, she is in good condition and may remain as clapped.*

Committee Minute 24th April 1840
 Character assigned First Mate *Wm. J. Clark*

