

REPORT of SURVEY for REPAIRS.

6411

[Signature]

No. 257 Survey held at London Date May 6. 18 1840
 on the Bk Bombay Master Turner? Purley P. Eastey
 Tonnage 1280 Built at Bombay When built 1809
 By whom built _____ Owners In Pirie & Co
 Port belonging to London Destined Voyage Bombay
 If Surveyed Afloat or in Dry Dock Blackwall

Original Survey, No. 835, 5036 Dated March 1839 Classed *A.1 ✓
 Port London 5047,

Repairs

At the present time in consequence of having been
 ashore - new iron piece of keel, gripe. Fore & main steps
 several planks under flat caulked from the keel up
 and re-coppered to the wale and damage effectually repaired
 The masts and Rigging are now being overhauled

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>1840</u>	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

In my opinion this Ship is fully eligible to remain
 as at present classed *A.1

George Bayley

The Amount of Fee.....£ / : / : is received by me, *[Signature]*

Special Damage Committee's Minute 2nd June 1840

Character assigned R. Asterisk Second Copper