

REPORT of SURVEY for REPAIRS.

Coppering 6481 Lon

No. _____ Survey held at London Date June 5 1840
on the St. Isabella Master Chenro
Tonnage 580 Built at London When built 1818
By whom built _____ Owners Dunbar & Co
Port belonging to London Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock Fletcher Dock

Original Survey, No. _____ Dated March 1839 Classed *F.1
Port London

Repairs

*Shutters caulked to water - freshened this
with yellow ochre*

*This ship presents a firm appearance throughout
& is free from any movement on her
fastenings*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <i>App to Wales 1840</i>	Standing & Running Rigging

General Observations and Opinion,
as required by the Instructions,

*In my opinion this ship is fully fit to
remain as classed *F.1*

George Bayley

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18 _____

Character assigned _____