

Coppering

REPORT of SURVEY for REPAIRS.

6525

No. _____ Survey held at London Date June 20 18 40
on the Back London Master Lamb
Tonnage 239 Built at London When built 1833
By whom built _____ Owners Lamb
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Globe Dock

Original Survey, No. _____ Dated May 1839 Classed 10A1
Port London

Repairs

*At the present time stripped and caulked
from keel to hale & recoppered*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c. <i>Overhauling</i>
Plank Shears	Counter	Sails <i>good & efficient</i>
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>1840</u>	Standing & Running Rigging

General Observations and Opinion,
as required by the Instructions,

*In my opinion this vessel is eligible to remain
as classed 10A1*

George Bayley

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18 _____

Character assigned _____