

REPORT of SURVEY for REPAIRS.

69/14

No. 5 Survey held at London Date May 14 1839
 on the Ship Malabar Master W. Black
 Tonnage 647 Built at London When built 1834
 By whom built Gunn & Co Owners Rymer
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Blackwall Dock

Original Survey, No. 141, 1704 Dated 1835 Classed 1241
 Port London 0347, dated 1840

Repairs *at the present time stripped - scraped right aloft. caulked throughout - sheathed with yellow metal upon Deck to the Water Mast Rigging & overhauling*

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Trussells (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper <u>1839</u>	Standing & Running Rigging

General Observations and Opinion, as required by the Instructions. *In my opinion this ship is entitled to remain as at present classed as a*
George Bayley

The Amount of Fee.....£ : : is received by me,
 Committee Minute 14th May 1840
 Character assigned Good

