

REPORT of SURVEY for REPAIRS.

6969

No. 123 Survey held at London Date Feb 1 1848
 on the Bk Chiefstain Master Heaton
 Tonnage 309 Built at Greenwich When built 1837
 By whom built _____ Owners Mr. Sully
 Port belonging to Greenwich Destined Voyage Swan River
 If Surveyed Afloat or in Dry Dock London Dock

Original Survey, No. 458 Dated 1837 Classed 12 A 1

Port of London

Repairs

At the present time Bottom stripped, caulked from the keel to the Gunwale and sheathed with yellow metal over paper.

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstans
Lower Deck Beams & Fastenings	Topsides	Pumps
Spurkettling	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears	Counter <u>Good</u>	Sails <u>Efficient</u>
Waterways	Plank & Treencails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchor No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinions as required by the Instructions.

Ship in a very high state of efficiency both in the hull, rigging and apparels. Lightly repaired.



© 2019

The Amount of Fee £ _____ is received by me,

Committee's Minute 12 A 1 1848

Character assigned 12 A 1

Lloyd's Register Foundation