

REPORT of SURVEY for REPAIRS.

7034
JH

No. 361 Survey held at LONDON Date Nov 9th 1888
 on the Bark Charles Master _____
 Tonnage 334 Built at Whitby When built 1805
 By whom built _____ Owners Douglas & Co.
 Port belonging to LONDON Destined Voyage Sobago
 If Surveyed Afloat or in Dry Dock Shop^o Chalmers Dry Dock

Original Survey, No. 1227, 2466, Dated May 1886 Classed A. 1
 Port LONDON 3708, 5292, 5780, 61123, 6933,

Repairs *At the present time having been dismantled
 New shafts Riggings -
 Stoppes - caulked from the keel up and
 recopied on paper 13 feet*

The Surveyor is also required to state the present Condition of the

Decks _____	Transoms _____	Windlass _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Capstan _____
Lower Deck Beams & Fastenings _____	Topsides _____	Pumps _____
Spirkettling _____	Wales _____	Masts, Yards, &c. _____
Plank Shears _____	Counter _____	Sails _____
Waterways _____	Plank and Trenails (Outside the Water's Edge) _____	Cables _____
Hatchway Comings _____	Rudder _____	Anchors No. of _____
Breasthooks _____	Copper <u>1138</u>	Standing & Running Rigging _____

General Observations and Opinion, as required by the Instructions, *In my opinion this report should remain as at present dated A. 1*

George Bayley

The Amount of Fee £ _____ is received by me.

Committee Minute 11th Dec. 1888

Character assigned A. 1

