

REPORT of SURVEY for REPAIRS.

1043
[Signature]

No. 538 Survey held at Londen Date Nov 19th 1830
 on the By Jordanson Master Jordanson
 Tonnage 2000 Built at Shield When built 1829
 By whom built _____ Owners Jordanson
 Port belonging to Londen Destined Voyage Leghau
 If Surveyed Afloat or in Dry Dock in the Dry Dock

Original Survey, No. 539, 2110, Dated _____ Classed Continued 9 Δ
38 3
 Port of Londen 3810, 4115, 4508, 6236, 6876,

Repairs At the present time Bottom is examined & Caulked
and Copperd over Belt to the ten feet mark up to the
sheathing on the upper course of the Bottom.

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c. <u>Good</u>
Plank Shears	Counter	Sails <u>Good</u>
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables <u>Sufficient</u>
Hatchway Comings	Rudder	Anchors No. of _____
Breasthooks	Copper	Standing & Running Rigging _____

General Observations and Opinions This vessel is in a very high state of efficiency,
 as required by the Instructions, both in the Hull & Masts and well deserving
her present Rate. © 2019

The Amount of Fee £ : : is received by me, [Signature]
 Committee Minute 11th Dec 1830 Lloyd's Register
 Character assigned Ant. B. A. & Assesd [Signature] Foundation