

ANNUAL SURVEYS.

7161

No. 28 Survey held at London Date Jan 7th 1841
 on the Barque "Barbara Gordon" Master Ritchie
 Tonnage 338 Built at Sunderland When built 1836
 By whom built _____ Owners Gordon & Co
 Port belonging to London Destined Voyage Stago
 Surveyed ~~at~~ in Dry Dock Mr Ritchie

Original Survey, No. 3381 Port of London Classed 1A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks _____	Cupatan _____
Upper Deck Beams & Fastenings <u>"</u>	Transoms <u>Not seen</u>	Pumps _____
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Spir-ketting <u>"</u>	Top-sides <u>Good</u>	Sails _____
Plank Shears <u>"</u>	Wales <u>"</u>	Cables _____
Waterways <u>"</u>	Plank and Treennils <u>"</u> <small>(Outside to the Water's Edge.)</small>	Anchors No. of _____
Hatchway Coverings <u>"</u>	Rudder _____	Standing & Running Rigging _____
	Windlass <u>"</u>	Copper <u>New 1837</u>

General Observations and Opinion, This Ship is in a very efficient State and
as required by the Instructions, may remain as classed; at the present time
Stripper, can't see from Mast to Gunwale, & Copper to the Water on upper

Committee Minute 26th Jan 1841

Character assigned 1A1 Good Ritchie

No. 668 Survey held at London Date Jan 21st 1841
 on the Barque "Stanford" Master _____
 Tonnage 346 Built at Cowes When built 1832
 By whom built _____ Owners Blyth
 Port belonging to _____ Destined Voyage _____
 Surveyed Afloat ~~at~~ London dock

Original Survey, No. 3866, 556 Port of London Classed 1A1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Breasthooks _____	Cupatan _____
Upper Deck Beams & Fastenings <u>"</u>	Transoms <u>Not seen</u>	Pumps _____
Lower Deck Beams & Fastenings <u>"</u>	Timbers of the Frame _____	Masts, Yards, &c. _____
Spir-ketting <u>"</u>	Top-sides <u>Good</u>	Sails _____
Plank Shears <u>"</u>	Wales <u>"</u>	Cables _____
Waterways <u>"</u>	Plank and Treennils <u>"</u> <small>(Outside to the Water's Edge.)</small>	Anchors No. of _____
Hatchway Coverings <u>"</u>	Rudder _____	Standing & Running Rigging _____
	Windlass _____	Copper _____

General Observations and Opinion, At the present time shifted a piece of plank sheen, (timbers good)
as required by the Instructions, can't see the waterways, & shifted 1 lower deck beam.
The Ship is in good condition and may remain
as classed

Committee Minute 26th Jan 1841

Character assigned 1A1 Good Ritchie

Lloyd's Register Foundation