

ANNUAL SURVEYS.

1288

No. 121 Survey held at London Date Mar 2 1841
 on the Ship Seal Master Burrows
 Tonnage 394 Built at Bristol When built 1833
 By whom built Hillhouse Owners Waters
 Port belonging to Bristol Destined Voyage Spain & New Zealand
 If Surveyed Afloat or in Dry Dock Station Dock

Original Survey, No. Bristol, 86, 1034 Port of London Jan 4 1840 Classed N.A.1.

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Top-sides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails <small>(Outside to the Water's Edge.)</small>	Anchors No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	

General Observations and Opinion, Top-sides Wales scraped clean forward and yard
 as required by the Instructions, found fastenings - Caulked from the top
up - In my opinion they might be removed
as elapsed 10 1/2

Committee Minute 5th March 1841 George Bagley

Character assigned 10 George Bagley

No. _____ Survey held at _____ Date _____ 184____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Original Survey, No. _____ Port of _____ Classed _____


The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Top-sides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treennails <small>(Outside to the Water's Edge.)</small>	Anchors No. of
Hatchway Coverings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion, as required by the Instructions,

Committee Minute _____ 184____

Character assigned _____



© 2019

Lloyd's Register Foundation