

REPORT of SURVEY for REPAIRS.

No. 708 Survey held at London Date March 15th 1847
 on the Barque "Annabella" Master Ward
 Tonnage 199 Built at Port Glasgow When built 1834
 By whom built _____ Owners King & Co
 Port belonging to Port Glasgow Destined Voyage _____
 Surveyed At in Dry Dock Mr. Ritchie's dock

Original Survey, No. 35 Dated _____ Classed 10 A1

Port Clyde, Lat. 2342, Lon 6308,

REPAIRS

At the present time, shipped off the Copper
 Caulked from Keel to Waterway shifted a plank on
 the Starboard side under the wale & frame very defective
 proceeded from a bad treenail: piece out in new timber
 very good; fitted a pair of stout Iron diagonal ^{braces} across
 the defective frame: Coppered the Bottom to wale
 on paper

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,

This vessel is in good condition. fit for the safe
 conveyance of any perishable goods too and from all
 parts of the world and in my opinion may remain
 as afloat

The Amount of Fee.....£ 1 : 0 is received by me,

Committee's Minute 6th April 1847

Character assigned 10 A1



© 2019

Lloyd's Register
 Foundation

LON 610-0112