

Champernownes **REPORT of SURVEY for REPAIRS.**

No. 7495 Survey held at LONDON Date Jan 15 1890
 on the Ship Mandarin Master _____
 Tonnage 425 Built at Ayrton When built 1874
 By whom built Giles Owners Rupert at Rhydymor
 Port belonging to LONDON Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Blackett's Dock

Original Survey, No. _____ Dated 1888 Classed 10 A 1
 Port Liverpool

Repairs at the present time called for to the valves on pumps and machinery - ship being -

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirketting	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Riggers

General Observations and Opinion,
 as required by the Instructions, My opinion in this ship is chiefly to
remain as classed 10 A 1

George Bayley

The Amount of Fee.....£ : : is received by me,

Committee's Minute _____ 18 _____

Character assigned _____