

REPORT of SURVEY for REPAIRS.

7524

No. _____ Survey held at London Date May 5th 1841
 on the Ship Arab Master _____
 Tonnage 414 Built at Stockton When built 1840
 By whom built 405 Owners Swine
 Port belonging to London Destined Voyage New Zealand
 Surveyed Afloat or in Dry Dock Ship: Curley Youngs

Original Survey, No. 157 Dated _____ Classed PA1
 Port Stockton

REPAIRS

At the present time, Caulked the Bottom & Lapped over Paper - lapped a 2nd Layer deck

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,


A good well built Ship for her class - fit for the safe conveyance of any perishable goods to and from all parts of the world, and in my opinion should remain as classed

The Amount of Fee.....£ _____ is received by me,

Committee's Minute 11th May 1841

Character assigned

Special to examine Bottom & ascertain damage - 2-2-0



© 2019

Lloyd's Register Foundation

LONGIO-0241