

# ANNUAL SURVEYS.

19144

No. <sup>222</sup> Survey held at London Date Sept 184 1  
 on the the promotion Master Coates  
 Tonnage 282 Built at India When built 1826  
 By whom built \_\_\_\_\_ Owners Coates  
 Port belonging to London Destined Voyage Constantinople  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 222, 26th, Port of London, Sept 7th, 1841, Classed \*A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettig <u>good</u>	Topsides <u>good</u>	Sails <u>Sufficient</u>
Plank Sheers	Wales	Cables <u>Good</u>
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchor No. of _____
Hatchway Comings	Rudder	Standing & Running Rigging
<u>impaired</u>	Windlass	Copper

General Observations and Opinion,  
 as required by the Instructions,

Two of the upper & two of the Hold Beams had been removed to admit of boilers, has now been replaced and properly secured and the mty remain as before

Committee Minute 21st Septe 184 1

Character assigned

Not Satisfactory Honourary

No. <sup>225</sup> Survey held at London Date 14 Sept 184 1  
 on the the Ruby Master Thompson  
 Tonnage 235 Built at London When built 1825  
 By whom built \_\_\_\_\_ Owners Post  
 Port belonging to Wales Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Afloat

Original Survey, No. 225, 26th, Port of London, Sept 14th, 1841, Classed \*A1

The Surveyor is required to state the present Condition of the

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettig <u>good</u>	Topsides <u>good</u>	Sails <u>Sufficient</u>
Plank Sheers	Wales	Cables <u>Good</u>
Waterways	Plank and Treennails (Outside to the Water's Edge)	Anchor No. of _____
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper

General Observations and Opinion,  
 as required by the Instructions,

Recently repaired for restoration and is in an efficient state & may remain as before

Committee Minute 21st Septe 184 1

Character assigned

Not Satisfactory

© 2019 Lloyd's Register Foundation