

# REPORT of SURVEY for REPAIRS.

1984

No. 363 Survey held at London Date Sept 17 184/1  
 on the St. Bolton Master \_\_\_\_\_  
 Tonnage 541 Built at Liverpool When built 1822  
 By whom built \_\_\_\_\_ Owners J. B. Hooper  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Leaving Dock

Original Survey, No. 1244, 2540 Dated 1839 3/15, 5/40. Classed A 1  
 Port Londra Left 7 years 1835

REPAIRS In consequence of damage. Shipped. 3 top Beams  
 14 lower Deck Beams. 14 upper Deck Beams, Lower Deck Shelf  
 Clamps Waterways. Knees & Standards. Shifter, New upper  
 & lower Decks complete Shakes of lower Deck planking -  
 7 pair of Iron Breast Rides extend from lower Deck  
 to Ridge - caulked throughout & thoroughly repaired -  
 New Foremast. Rigging entirely overhauled -  
 Coppered on paper to the wale

## Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Top-sides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchor No. of
Breasthooks	Copper <u>1841</u>	Standing & Running Rigging

General Observations and Opinion, In my opinion this ship is eligible for service  
 as classed A 1

George Bayley

The Amount of Fee.....£ 3 : : : is received by me, officer

Committee's Minute 1st October 1841

Character assigned See Report

Lloyd's Register  
 Foundation