

REPORT of SURVEY for REPAIRS.

Specie for Damage

1999

No. 122 Survey held at London Date Sept 18 to 27th 1841
 on the Brig Sedone Master Aickton
 Tonnage 167 Built at Greenharrow When built 1829
 By whom built _____ Owners Aickton & Co
 Port belonging to London Destined Voyage Opente
 If Surveyed Afloat or in Dry Dock New Coane

Original Survey, No. 20 Dated _____ Classed A. 1

Port Portsmouth, London 3788, 1900, 6850,
 REPAIRS Repaired & Stanchion of Ceiling Starboard side & one belay
hook in the Sackton side. & 3 through bolts. &
Ran Chocks at the floor & posts & heels with 10 ft bolts;
down into & removed all the beams in the Starboard side
from the fore mast to abate the main Rigging, & pulled
the vessel all over, & 4 new four pairs of Diagonal knee
pieces to the side beams, running down to bulk & into
the floor; and drove a number of additional ^{this} bolts in
the belay strakes (of Copper)

Present Condition of the

Decks <u>fair good state</u>	Transoms <u>sub. down</u>	Windlass _____
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good & new run</u>	Capstan _____
Lower Deck Beams & Fastenings <u>good</u>	Topsides _____	Pumps _____
Spirkettling _____	Wales _____	Masts, Yards, &c. _____
Plank Shears _____	Counter _____	Sails _____
Waterways _____	Plank & Treennails (Outside to the Water's Edge)	Cables _____
Hatchway Comings <u>good</u>	Rudder _____	Anchor No. of _____
Breasthooks _____	Copper _____	Standing & Running Rigging _____

General Observations and Opinion, This vessel when opened presented a good square sound
frame of timber: she is throughout in an efficient state fit for the
service of the Company & in my opinion should remain
so classed

The Amount of Fee £ 1 is received by me, Wm. L. Clark

Committee's Minute 5th October 1841

Character assigned Fit for service

Special £2.2.0

Lloyd's Register
Foundation