

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date 15 Oct 1838
 on the Fish Fairilla Master Healey
 Tonnage 333 Built at Newcastle When built 1829
 By whom built _____ Owners Parton & Co
 Port belonging to London Destined Voyage Lamaine
 If Surveyed Afloat or in Dry Dock Rep'd & Shuttles Dry Dock

Original Survey, No. _____ Dated _____ not Classed
 Port _____

Repairs At the present time the broadsheeting taken off Upper Gun - Caulked & recoppered but not shuted

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spilcketting	Wales	Masts, Yards, &c.
Plank Sheers	Counter	Stills
Waterways	Plank & Treennails (Outside to the Frame's Edge)	Cables
Halfway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion,
 as required by the Instructions,

This vessel appears to be in good and efficient condition

The Amount of Fee £ _____ is received by me

Committee Minute _____ 18 _____

Character assigned _____

Lloyd's Register
 Foundation