

REPORT of SURVEY for REPAIRS.

No. _____ Survey held at Liver Date June 5th 1880
 on the Bk David Luckie Master Pitchie
 Tonnage 320 Built at Sunderland When built 1837
 By whom built _____ Owners E Luckie
 Port belonging to Liver Destined Voyage Pomerania
 If Surveyed Afloat or in Dry Dock on Smiths Dry Dock

Original Survey, No. _____ Dated 1837 Classed 10 A 1
 Port of Liver

Repairs At the present time having been on shore on the Crows necks has had saws that found aft, stepped, several staved beams driven out & renewed, one new Breasthook, additional stemming knees to the Beam under the Drake Deck, and Cedarwood stave aft, caulked overall by Reifford over Galt

The Surveyor is also required to state the present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Sheers	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	Copper	Standing & Running Rigging

General Observations and Opinion
 as required by the Instructions,

Transom is in a very high state of efficiency both in the Hull & Masts are in a very satisfactory condition
 Map 10 A 1

The Amount of Fee £ : : is received by me,

Committee's Minute _____ 18

Character assigned _____