

REPORT of SURVEY for REPAIRS.

10,345

No. 1 Survey held at London Date Jan^{ry} 8th 12 1844
 on the Ship Pictiers Master H. Denney
 Tonnage 756 Built at Sunderland When built 1843 Registered on 1844
 By whom built Owners Duncan Dunbar
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Mr^s Greene Dock

Last Survey, No. 2405 Classed G A

Port Sunderland

REPAIRS Caulked & sheathed with yellow metal over paper

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank and Treenails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of
Breasthooks	<u>Painted Yellow Metal Jan^{ry} 1844</u>	Standing & Running Rigging

General Observations and Opinion, Ship in a very good & efficient state to retain her present class

Auth. & M. L. L.

The Amount of Fee.....£ : : is received by me,

Committee's Minute 10th January 1844

Character assigned G A 1 *Jan 10*



© 2019

Lloyd's Register Foundation

LON 616 - 0339