

REPORT of SURVEY for REPAIRS.

10, 464

No. 480 Survey held at London Date Jan^y 30. 31 Feb 3. 23rd Mar 5 1844
 on the Bk John Hullett Master Austin
 Tonnage 284 Built at Sunderland When built 1841
 By whom built _____ Owners St & Blyth
 Port belonging to London Destined Voyage Mauritius
 If Surveyed Afloat or in Dry Dock Wine Dock
 Last Survey, No. 8392 Feb 1843 Classed 9 A 1

Port London
 REPAIRS At the present time shipped - Three additional Hold Beams put in together with five pairs Iron Hanging knees to the Lower Deck and five pairs of Staple Standards - One Half Beam shifted. The Channel work altered and the Bolts put through the upper blocks & staves, all new Channels - Caulked from the keel up over to Watway Letts and Coppered to the rule

Present Condition of the

Decks	Transoms	Windlass
Upper Deck Beams & Fastenings	Timbers of the Frame	Capstan
Lower Deck Beams & Fastenings	Topsides	Pumps
Spirkettling	Wales	Masts, Yards, &c.
Plank Shears	Counter	Sails
Waterways	Plank & Treennails (Outside to the Water's Edge)	Cables
Hatchway Comings	Rudder	Anchors No. of 3. 1. 1
Breasthooks	Copper <u>Tell 1844</u>	Standing & Running Rigging

General Observations and Opinion, In our opinion this vessel is eligible to remain as classed 9 A 1

Special Appointment for future 2.2

George Bayley
Nathaniel P. W. L. W.

The Amount of Fee.....£ : : is received by me,

Committee's Minute 8th March 1844

Character assigned 9 A 1



© 2019

Lloyd's Register
Foundation

Lon 616-0462