

ANNUAL SURVEYS.

10,488

No. 515 Survey held at London Date 23 Feb 7 1844
 on the Schooner "Mary" Master Cloid
 Tonnage 160 Built at Spilwick When built 1835
 By whom built _____ Owners Travers & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock on Crisp's Ways

Original Survey, No. 10,026 Port of London Classed 11 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Way Caulked Good</u>	Transoms <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Pumps <u>Good</u>
Lower Deck Beams & Fastenings _____	Topsides _____	Masts, Yards, &c. <u>Sufficient</u>
Spirkettling _____	Wales _____	Sails _____
Plank Shears _____	Counter _____	Cables _____
Waterways _____	Plank and Treenails (Outside to the Water's Edge.) _____	Anchors No. of <u>2 B 1 St 1 K</u>
Hatchway Comings _____	Rudder <u>Overhauled</u>	Standing & Running Rigging <u>Good</u>
Breasthooks _____	Windlass _____	<u>Yellow Metal New</u>

General Observations and Opinion,
 as required by the Instructions,

From having been on shore, the bottom has been stripped
 Caulked and tacked with Y Metal on dry paper
 She is in most efficient Condition and may

Committee Minute 10th March 1844 Continue as Classed

Character assigned 11 A 1 Joseph Whitehead

Spent £4 1

No. 215 Survey held at London Date 5th 78 March 1844
 on the Ship "Simandira" Master J Skinner
 Tonnage 432 Built at Little Hampton When built 1841
 By whom built _____ Owners J Nigou
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock in New Crane Dock

Original Survey, No. 9524 Port of London Classed 11 A 1

The Surveyor is required to state the present Condition of the

Decks <u>Good</u>	Transoms <u>Good</u>	Capstan _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>Not Seen</u>	Pumps <u>Good</u>
Lower Deck Beams & Fastenings _____	Topsides <u>Good</u>	Masts, Yards, &c. <u>Sufficient</u>
Spirkettling _____	Wales _____	Sails _____
Plank Shears _____	Counter _____	Cables _____
Waterways _____	Plank and Treenails (Outside to the Water's Edge.) _____	Anchors No. of <u>3 B 1 St 1 K</u>
Hatchway Comings _____	Rudder <u>Bands Refastened</u>	Standing & Running Rigging <u>Good</u>
Breasthooks _____	Windlass <u>Good</u>	<u>Yellow Metal</u>

General Observations and Opinion,
 as required by the Instructions,

From having been on shore in the River Hooghly the
 bottom at present has been stripped and the Rudder
 bands refastened to the wales the

Committee Minute 10th March 1844

Character assigned 11 A 1 Mr. Nigou

Spent £4 2