

ANNUAL SURVEYS.

11583

No. 34 Survey held at London Date May 3rd to May 10th 1845
 on the Duke of Bedford Master R Thornhill
 Tonnage 685 Built at Calcutta When built 1820
 By whom built _____ Owners Thornhill
 Port belonging to London Destined Voyage India
 If Surveyed Afloat or in Dry Dock Gloucester Dock & 2^d Dock.

Last Survey, No. 10243 Port of London Classed *E1

The Surveyor is required to state the present Condition of the

Decks <u>good</u>	Transoms <u>good where seen</u>	Capstan <u>good</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame <u>good where seen</u>	Pumps <u>2^d</u>
Lower Deck Beams & Fastenings <u>good</u>	Topsides <u>caulked. good</u>	Masts, Yards, &c. <u>All good - some spare spars.</u>
Spirketting <u>good</u>	Wales <u>caulked. good</u>	Sails <u>2¹/₂ suits</u>
Plank Shears <u>good</u>	Counter <u>good</u>	Cables <u>320 fms Chain & Stream good Hawsers.</u>
Waterways <u>(thick) good</u>	Plank and Treenails <u>the bottom is sheathed</u> (Outside to the Water's Edge.)	Anchors No. of <u>3 Bower / Stream 1 keg.</u>
Hatchway Comings <u>good</u>	Rudder <u>2^d and in good order</u>	Standing & Running Rigging <u>good, refitted.</u>
Breasthooks <u>good</u>	Windlass <u>(1st new) with Patent purchase.</u>	Copper <u>New 1/2 in over sheathing.</u>

General Observations and Opinion,
 as required by the Instructions,

This ship has been into the dry dock, her bottom stripped of G.M. and recovered with the ^{new Y.M.} frame - the hood ends both fore & aft have been caulked, and the caulking of the bottom under the sheathing has been examined & found good -

Committee Minute

23rd May 1845 world and may therefore continue as at present

Character assigned

*E1 Attended with the asterisk.

Augustine Henry
Hurstway

No. 160 Survey held at London Date 19 May 1845
 on the St. Sumatry Master _____
 Tonnage 325 Built at Scorbe When built 1840
 By whom built Small Owners Small
 Port belonging to Scorbe Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 10380 Port of London Classed 11A1

The Surveyor is required to state the present Condition of the

Decks _____	Transoms _____	Capstan _____
Upper Deck Beams & Fastenings <u>beam</u>	Timbers of the Frame _____	Pumps _____
Lower Deck Beams & Fastenings <u>do</u>	Topsides _____	Masts, Yards, &c. _____
Spirketting _____	Wales _____	Sails <u>affluent</u>
Plank Shears <u>good</u>	Counter <u>good</u>	Cables _____
Waterways _____	Plank and Treenails _____ (Outside to the Water's Edge.)	Anchors No. of _____
Hatchway Comings _____	Rudder _____	Standing & Running Rigging _____
Breasthooks _____	Windlass _____	Copper <u>1844</u>

General Observations and Opinion,
 as required by the Instructions,

she appears in the most efficient condition
and may remain as at present

Committee Minute

23rd May 1845

Character assigned

11A1

Hurstway



© 2019

Lloyd's Register
 Foundation