

ANNUAL SURVEYS.

12846

No. 404 Survey held at London Date 16 Sept 1846
 on the BK "Brunette" Master B. Cousins
 Tonnage 285 Built at Sunderland When built 1841
 By whom built _____ Owners Cousins
 Port belonging to London Destined Voyage Ceylon
 If Surveyed Afloat or in Dry Dock in Curling off Dock

Last Survey, No. 11332Port of LondonClassed YA1

The present Condition of the

Decks	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways	<u>one new of iron in stern deck</u>	Pumps
Comings	Breasthooks and Stemson <u>Good</u>	Boats
Upper Deck Beams & Fastenings	Transoms, Pointers, and Crutches	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings	Timbers of the Frame	Sails
<u>one beam Clamped</u> <u>Good</u>	Keelsons	Anchors No. of <u>3. 1/2</u>
Planksheers <u>Caulked</u>	Clamps and Shelves	Cables
Sheerstrakes <u>Caulked</u>	Ceiling	Hawsers and Warps
Topsides <u>Do</u>	Rudder	Standing & Running Rigging
Wales <u>Do</u>	Copper <u>Repaired</u>	
Plank (Bottom) and Counter		

General Observations and Opinion,

at Present Docked to inspect the state of yellow metal which was repaired - an additional iron breasthook has been fitted between decks - one hole beam Clamped

Committee Minute

1846

Character assigned

YA1 in efficient Condition and May remain as Clamped 1/2 Fletcher

Certificate (if required)

No. 274 Survey held at London Date 26 Sept 1846
 on the BK Maria Master _____
 Tonnage 420 Built at Yarmouth When built 1836
 By whom built _____ Owners Gardner & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Fletchers Dock

Last Survey, No. 12172Port of LondonClassed YA1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings	Keelsons	Sails <u>and</u>
<u>Caulked</u> <u>Good</u>	Clamps and Shelves	Anchors No. of <u>3. 1/2</u> <u>Sufficient</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	<u>one new</u> Hawsers and Warps
Wales	Copper <u>Repaired</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

This Vessel appears in efficient Condition and May continue as Clamped

Committee Minute

1846

Character assigned

YA1 in efficient Condition and May continue as Clamped 1/2 Fletcher



© 2019

Lloyd's Register Foundation