

13082.
REPORT of SURVEY for REPAIRS.

No. _____ Survey held at London Date January 9th 1847
on the "Margaritha" Master Buair
Tonnage 389 Built at Sweden When built 1806
By whom built _____ Owners R. Thornton
Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____

Last Survey, No. 12299 Port London Classed M.

REPAIRS

For particulars see Letter attached

Present Condition of the

| | | |
|-------------------------------------|--|----------------------------------|
| Decks _____ | Treenails _____ | Windlass and Capstan _____ |
| Waterways _____ | Breasthooks and Stemson _____ | Pumps _____ |
| Comings _____ | Transoms, Pointers, and Crutches _____ | Boats _____ |
| Upper Deck Beams & Fastenings _____ | Timbers of the Frame _____ | Masts, Yards, &c. _____ |
| Lower Deck Beams & Fastenings _____ | Keelsons _____ | Sails _____ |
| Planksheers _____ | Clamps and Shelves _____ | Anchors No. of _____ |
| Sheerstrakes _____ | Ceiling _____ | Cables _____ |
| Topsides _____ | Rudder _____ | Hawsers and Warps _____ |
| Wales _____ | Copper _____ When put on _____ | Standing & Running Rigging _____ |
| Plank (Bottom) and Counter _____ | | |

General Observations and Opinion,

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute _____ 18 _____

Character assigned _____



© 2019

Lloyd's Register
Foundation

LON 622-0153