

REPORT of SURVEY for REPAIRS.

No. 13995 Survey held at London Date December 21 1847
 on the Br Aden Master Wadde
 Tonnage 357 Built at Sunderland When built 1841
 By whom built _____ Owners R Bicks
 Port belonging to London Destined Voyage Robert Town
 Surveyed Afloat or in Dry Dock Smethkin Dock

Last Survey, No. _____ Classed GA

Port _____

REPAIRS

This vessel has been in dry dock since the 13th Inst, and found upon enquiry she had been surveyed by the surveyor to the insurance company having been on shore on Berwick shunts, and is reported to have received the following repairs; which appears to be correct

" Shipped, hung, caulked from the keel to the waterway seam, several
 " started keelnails renewed, scraped bright from the turn part of the
 " wales to the gunwale, two planks in the topsides shifted in the
 " way of the chain plate bolts with track, one broken iron knee
 " in the hold beams replaced, navel head refitted, and sheathed with
 " Yellow Metal over felt

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, *The stern and inside has been seen by Mr. Crutcher; from her general good appearance and the efficient state of repairs and opinion she may retain her present shape*

W. Wadde

The Amount of Fee.....£ : : is received by me,

Certificate (if required) : :

Committee's Minute _____ 18

Character assigned _____



© 2019

Lloyd's Register Foundation

LON 624-0179