

REPORT of SURVEY for REPAIRS.

No. 190 Survey held at London Date Feb 28 to Mar 6 1849
 on the Brig Savinia Master J Keller
 Tonnage 161 Built at Lyme When built 1825
 By whom built _____ Owners Mr Rogers
 Port belonging to London Destined Voyage Appledore to Repair
 If Surveyed Afloat or in Dry Dock Afloat off Gun Dock, and in the London Dock

Last Survey, No. 14095 Port London Classed 11 * AE /
 C 4 3 mo 40

REPAIRS

From the external appearance a Notice Card was left on the 22nd Feb^{ry} recommending that the Outside Planking above the yellow metal sheathing also the Planksheer and Waterway be scraped bright all defects removed and the Deck ends and at other parts be repaired "

On the 5th Ins^t we attended and found the Sheer Strakes and Topsides scraped bright, Planksheer and Waterway not scraped and the Wales but partially so.

On the Starb^d side as far as could be seen the Planking abeam of raised Quarter Deck, the whole of Sheer Strake (except the Fore Head) and the whole of Topsides Planking abeam of Fore and Main Rigging are in such a condition as to unfit her for her present or ~~the~~ character. The Port side is in the same condition except that a missing Piece of Planksheer is removed and not replaced //

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

The Owner declines doing any Repair in London, but states "he intends sending her to Appledore there to undergo a thro' overhaul and Repair"

The Amount of Fee.....£..... is received by me,

Special.....

Certificate (if required)

Committee's Minute

Character assigned

LON626-0188



© 2019

Lloyd's Register Foundation