

18134

REPORT of SURVEY for REPAIRS.

No. ⁸⁷ Survey held at London Date 11th Feb 1853
 on the Ship Asia Master _____
 Tonnage 523 Built at Calcutta When built 1815
 By whom built _____ Owners Wall & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Young & Co Dock

See p. 12 back

Last Survey, No. 16725 Port London Classed *A, A

REPAIRS

^{SS 1846}
 Docked at present to examine the state of the bottom the yellow metal was found smooth & good. - Rattings have been cut from the flooring planks forward and Caulked and the Pludder bands have been refastened.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Top-sides	Radder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

Good

Good

Good

Sufficient

General Observations and Opinion,

This Vessel appears in good and efficient condition and fit to remain as Cargo

The Amount of Fee £ _____ is received by me, N. H. H. H.

Special 1 : 1 : SH

Certificate (if required) _____

Committee's Minute 8th April 1853

Character assigned 1st 1st

Special £ 1. 1. -

Lloyd's Register Foundation

LON 633-0072