

REPORT of SURVEY for REPAIRS.

18485

No. 32 Survey held at Witchamper Date Aug 6th 1853
 on the Bris Satelaff Master M. Patrass
 Tonnage 392 Built at Prince Edward Island When built 1849
 By whom built _____ Owners Maxwell
 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Pitchers dry Dock Northfleet and W. Brindley

Last Survey, No. 17907 Port London Classed 1-A1

REPAIRS At present for Damage Particulars in Special Report.

Line stripped off the bottom and after piece of Main Keel removed and renewed with American Black Elm and 200 say two hundred Treennails and several bolts in bilges and Sides of Holders. fore foot and girth repaired. the Bottom Caulked to Wales and re-sheathed with Lime on Sate.
 The following exclusive from damage one plank of Wales on port side being wormed now renewed with Oak pine and several cut out where wormed and made secure by piecing

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good when seen</u>	Windlass and Coppen <u>Good</u>
Waterways <u>Do</u>	Breasthooks and Stenson <u>Do</u>	Pumps <u>Do</u>
Comings <u>Do</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>Good Safe</u>
Upper Deck Beams & Fastenings <u>Good when seen</u>	Timbers of the Frame <u>Good when seen</u>	Masts, Yards, &c. <u>Do</u>
Lower Deck Beams & Fastenings <u>Seen</u>	Keelsons <u>Good</u>	Sails <u>Not Sailed</u>
Planksheers <u>Good</u>	Clamps and Shells <u>Do</u>	Anchor No. of <u>3 B 15 16</u>
Sheerstrakes <u>Do</u>	Ceiling <u>Do</u>	Cables <u>Safe</u>
Top-sides <u>Do</u>	Rudder <u>Do</u>	Hausers and Warps <u>Do</u>
Wales <u>Do</u>	Copper <u>Lime</u> When put on <u>Aug 1853</u>	Standing & Running Rigging <u>Good</u>
Plank (Bottom) and Counter <u>Do</u>		

General Observations and Opinion, This vessel appears to be in good Condition at the present time and in my opinion fit to remain as Classed

The Amount of Fee.....£ 3 : : is received by me,

Special..... 4 : 4 : Y M

Certificate (if required).....

Committee's Minute 16th Sept 1853

Character assigned 4 A 1 Good repair