

REPORT of SURVEY for REPAIRS.

18657

No. 626 on the Bk. "Melbourne" Survey held at London Date 5th 26th Dec 1853
 Master Caroline
 Tonnage 594 Built at Wm. Sexton When built 1852
 By whom built _____ Owners Hyde, Hodge, & Co
 Port belonging to London Destined Voyage Honduras
 If Surveyed Afloat or in Dry Dock Afloat in the West India Dock

Last Survey, No. 11920 Port Liverpool Classed 4 A1

REPAIRS

At the present time under Special Survey for Damage Particulars in Special Report.

Three new lower masts. Three topmasts, two topgallant masts, two topsail and two topgallant yards new topmast and topgallant rigging, and lower rigging refitted.

Bulworks and Round house repaired.
 Iron Tiller on Rudder repaired, new Head Nails on port side.

Waterway seams and plank sheer caulked
 Thirty fathoms of Bower Chain and one Bower Anchor and one new House pipe.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

This vessel is now in good Condition and fit to remain as classed

M. M. Intyre

The Amount of Fee.....£..... is received by me,

Special.....

Certificate (if required) :

Committee's Minute 9th Decr 1853

Character assigned 4 A1



© 2019

Lloyd's Register Foundation

1700-53-0071