

19626

REPORT of SURVEY for REPAIRS.

No. 13 on the Bark Guadalete Survey held at London Date 24th April 1855
 Tonnage 335 Built at Mells When built 1834
 By whom built 273 Owners W C Riley & Co
 Port belonging to London Destined Voyage Badiz
 If Surveyed Afloat or in Dry Dock Township Dry Dock

Last Survey, No. 19225 Port London Classed SA1

REPAIRS

at present under survey for damage from having been aground. More of particulars in special report. Metal sheathing stripped off - hung in shores caulked from keel to 2' seam inside of waterways. Bolts in iron riber straps (broken) renewed & the bottom resheathed with yellow metal - on plank.

Present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	<u>efficient</u>
Waterways		Breasthooks and Stemson		Pumps	<u>D</u>
Comings		Transoms, Pointers, and Crutches		Boats	<u>D</u>
Upper Deck Beams & Fastenings	} <u>efficient</u>	Timbers of the Frame	} <u>order</u>	Masts, Yards, &c.	<u>D</u>
Lower Deck Beams & Fastenings		Keelsons		Sails	<u>well found</u>
Planksheers	} <u>Good</u>	Clamps and Shelves	} <u>where seen</u>	Anchors	No. of <u>3 B 1 1/2 1 R</u>
Sheerstrakes		Ceiling		Cables	<u>B 1 1/2 1 1/2</u>
Topsides		Rudder		Hawsers and Warps	<u>7 1/2 5 3 1/2</u>
Wales	} <u>D D</u>	Copper	<u>Yel Met.</u> When put on <u>now</u>	Standing & Running Rigging	<u>D</u>
Plank (Bottom) and Counter					

General Observations and Opinion,

Now in efficient order - form unimpaired and eligible to remain as classed A1.
 Thomas Alexander

The Amount of Fee.....£..... is received by me,

Special..... 2 : 2 : -

Certificate (if required) : 5 : -

Committee's Minute 1st May 1855

Character assigned SA1

Special on Dam & Report £2.2



© 2019 Lloyd's Register Foundation
 LV635-0515