

REPORT of SURVEY for REPAIRS.

19980

No. 587 Survey held at London Date Oct to 1855
 on the SS Julia Master Clegg
 Tonnage 230 Built at Tynish When built 1830
 By whom built _____ Owners Tennant
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock In Limetula Shipway

Last Survey, No. 18870 Port London Classed 12 Feb 1
C 4 54

REPAIRS

At the present time. The outside Planking from lower part of Wales upwards scraped bright intending to undergo Special Survey Rule 60, about 100 feet of Planking in each Tapside has been renewed, but the condition of the remaining portion of Tapside Planking, Wales, Black Stakes, several of the Top Timbers and a large portion of Sheer Stakes is such as to cause the Owner to decline repairing for any character.

Present Condition of the

| | | |
|-------------------------------|----------------------------------|----------------------------|
| Decks | Treenails | Windlass and Capstan |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Keelsons | Sails |
| Planksheers | Clamps and Shelves | Anchors No. of |
| Sheerstrakes | Ceiling | Cables |
| Topsides | Rudder | Hawsers and Warps |
| Wales | Copper | Standing & Running Rigging |
| Plank (Bottom) and Counter | When put on | |

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

From the condition above stated the Owner respectfully declines repairing for any character, and we beg to recommend that her present character be expunged.

The Amount of Fee.....£ 10 10 0 is received by me,

Special Fee for attendance 10 10 0

Certificate (if required) _____

Committee's Minute 23rd October 1855

Character assigned Exchange Character

Thos Alexander

© 2019

Lloyd's Register
Foundation

LON636-0277