

20135

REPORT of SURVEY for REPAIRS.*and Change of owners*

No. 264 on the Ship "Simandra" Master Ellis Survey held at London Date 28th January 1856
 Tonnage 382 Built at Littlehampton When built 1841
 By whom built _____ Owners E. Coleman

Port belonging to Hull Destined Voyage _____

If Surveyed Afloat or in Dry Dock Afloat and in Bridge dry dock

Last Survey, No. 17928 Port London Classed 11 A 1
 Contd 52 - 4 52

REPAIRS

The first saw this vessel in the West India Dock basin and were informed that she was going into a dry dock for the purpose of being surveyed - a request was afterwards left at the office and on surveying the vessel, we found it necessary to recommend "that the defective planks in the Blackstrakes, Wales & bottom ~~in~~ buttocks already seen, be removed, and the ship examined throughout," before being reported to the Committee as being fit for any character!!

S. W. W.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,**Caulking of Bottom, Deck, & Waterways.**

In consequence of the defective planking not being removed as recommended; we are of opinion, that this vessel is not eligible for any class, and therefore

The Amount of Fee.....£ : : is received by me, recommend his Character
 Special..... : : to be expunged
 Certificate (if required) : : Thos. W. Wain.

Committee's Minute 1st February 1856

Character assigned Expunge Character

notice to remove by 1 Feb

LL

deferred write owner
for 1 Feb
for 1 Feb

© 2019 Lloyd's Register Foundation