

REPORT of SURVEY for REPAIRS.

No. 153 Survey held at London Date Feb 29th 1856
on the Schooner "Isabel" Master J. Cargile
Tonnage 153 Built at Hastings When built 1831
By whom built _____ Owners J. J. Adam
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Mountain Slip

Last Survey, No. 19024 Port London Classed Post 1/2 for 84 ^{12 1/2}

REPAIRS

Found the ceiling in the hold on each side amidships very defective, and left Notice Card with the Captain requesting the same to be renewed, and the hold to be properly cleared in order to examine the extent of the defects. The vessel has since left the slip without being repaired.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper When put on	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

I am of opinion that this vessel in her present condition is not fit for the A1. class; and beg to submit the same to the consideration of the Committee.

The Amount of Fee.....£..... is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 19th February 1856

Character assigned

Expunged Character
Notice to Owner
AD 20 2007



© 2019

Lloyd's Register
Foundation

LON636-0462