

REPORT of SURVEY for REPAIRS.

No. 431 Survey held at London Date 8th March 1856
 on the Barque "British Isles" Master Sagers
 Tonnage 331 Built at Sunderland When built 1837
 By whom built 397 Owners Rodrick
 Port belonging to London Destined Voyage _____

If Surveyed Afloat or in Dry Dock On Young's ways, & afloat W.I. Dock

Last Survey, No. 19190 Port London Classed 10
C 3 54

REPAIRS**Remarks -**

On surveying this ship, with a view to her classification, I found it necessary to recommend her to be scraped from the Copper line upwards. This recommendation having been complied with, it was found that the Sheerstrakes and Topsides were very defective -

Present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,**Caulking of Bottom, Deck, & Waterways.**

As the owners decline entering into the repairs necessary for the vessels efficiency, I cannot recommend her for classification on any character -

Richard Abthell

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 14th March 1856

Character assigned Record date of Survey

Charge for Special
 attendance £ 1 1 0

© 2019

Lloyd's Register
Foundation