

REPORT of SURVEY for REPAIRS.

204478

No. 599 Survey held at London Date 16th July 1856
 on the 43^h "Glydside" Master _____
 Tonnage 221 Built at Port Glasgow When built 1841
 By whom built _____ Owners Wright & Co
 Port belonging to Liverpool Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Fore & aft dry dock

Last Survey, No. 11183 Port Liverpool Classed 8 A. 1
 Post 50 5 52

REPAIRS

July 10th - On examining this vessel found several very defective planks in the Topsides and wormed planks in the wales, and therefore sent the following Notice Card Recommending, "the defective planking in the Topsides and Wales to be removed"

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

This vessel has gone out of dock without the recommendations being attended to, and I am informed by Mr. Mills that the owners decline repairing her for character.

We are of opinion that she is at present in an inefficient state

The Amount of Fee.....£ : : is received by me, and therefore recommend
 Special..... : : her character to be expunged -

Certificate (if required) : :

Committee's Minute 18th July 1856

Character assigned Expunge Character

Thos. W. Wawn

T. B. B. 19

Notice to owners

[Signature]

Lloyd's Register
 Foundation

LON 637-0159